



**Erede Rossi Silvio**  
azienda agricola trocicoltura















## Controllo della profondità della falda idrica



**Impianto:** Via Madonna dei calcinai, 2 Sefro (MC)

## REGISTRO PROFONDITA' FALDA

N.	DATA	N. POZZO	PROFONDITA' POZZO [m]	PROFONDITA' FALDA DAL PIANO CAMPAGNA [m]	PROFONDITA' FALDA RILEVATA [m]	FIRMA
1	16/04/2014	1	4,00	3,00	2,80	
2	21/10/2014	2	4,00	3,00	3,30	
3	22/04/2015	3	4,00	3,00	2,90	
4	22/10/2015	4	4,00	2,80	3,20	
5	21/04/2016	5	4,00	2,50	2,80	
6	24/10/2016	7	5,00	2,50	3,20	
7	18/04/2017	8	5,00	3,00	2,90	
8	16/10/2017	9	5,00	3,00	3,00	
9	16/04/2018	10	5,00	3,00	2,80	
10	09/10/2018	1	4,00	3,00	2,70	
11	08/04/2019	2	4,00	3,00	2,90	
12	21/10/2019	3	4,00	3,00	2,80	
13						
14						
15						
16						
17						
18						
19						
20						
21						
22						
23						
24						
25						
26						
27						
28						
29						
30						